

GENERAL CERTIFICATE OF CONFORMITY Contains: WG1048E2, WG1048E2BLK, WG1048E2GR, or WG1048E2DGR Description: 8" Round Suction Outlet Cover

Ratings: Open Area: <u>8.1 sq-in</u>

Certified to Comply with Section 1404 of the Virginia Graeme Baker Act (VGB) Pool & Spa Safety Act codified at 16 CFR part 1450, when installed on the listed products below. Certification by reports dated July 2019 and/or July 2020 and March-2009.

Manufactured: After Oct 1, 2020, by a Division of Hayward Industries, Inc. at K4-A, 214028 Block K4- A, Export Processing Zone Wuxi New District Jiangsu Province PRC 214028, China; or at One Hayward Industrial Drive, Clemmons, NC 27012.

Certified by Hayward Industries Inc. 400 Connell Drive, Suite 6100, Berkeley Heights, NJ 07922, Phone 908-355-7995

Contact at www.hayward-pool.com

Record Custodian is Customer Service at <u>www.hayward-pool.com</u>. Email: <u>https://www.hayward-pool.com/shop/en/pools/contactForm</u>

Hayward Pool Products P.O. Box 5100 Clemmons, NC 27012-5100, Phone: 908-355-7995

To our customers, the Serial Number is a 17 digit number, preceded by letters "SN"

The Serial# Code: 21121005456789001

•First 2 digits are "21", conforming to UCC-128 symbology, signifying a serial #

•The 3rd – 4th digits are the manufacturing "plant" code (12 for Clemmons, 21 for Wuxi, China)

•The 5th – 8th are "year & month" of the date of manufacture and assembly

•The 9th – 17th are "unique serialized number" for each product

Tested to: ANSI/APSP 16 -2017 per Section 1404 of the Virginia Graeme Baker Act (VGB) Pool & Spa Safety Act. Tested by NSF International, 789 Dixboro Road, Ann Arbor, MI 48113,


Phone 734-769-8010 in 2018. Certificate at: <u>http://info.nsf.org/Certified/Pools/Listings.asp?Company=21600</u>

Date of Installation:____

Suction outlet components have a finite life, the cover/grate as well as the hardware shall be inspected frequently and replaced at least every <u>**7 years**</u> from the date of installation, or if found to be damaged, broken, cracked, missing, or not securely attached.

If the cover/grate cannot be securely attached into the sump, a replacement insert kit WG1048EKIT, with instructions, is available. If this kit fails to allow the cover to be securely attached, the sump shall be replaced.

Hayward Pool Products acknowledges that it is a federal crime to knowingly and willingly make materially false, fictitious, or fraudulent statements, representations, or omissions on this certification.



USED ON THE FOLLOWING SERIES AND NO OTHER: WG1030

WG1030 WG1048 WG1051 WG1052 WG1053 WG1054 WG1153 WG1154



Warning – Suction Entrapment Hazard.

Suction in suction outlets and/or suction outlet covers which are installed in a small area and/or below the surrounding surface can cause severe injury or death due to body entrapment hazard.

To reduce the risk of body entrapment, installation of the field fabricated sumps must be such that the top of the mounted cover is a minimum of 1 1/2" above the finished pool surface over an area larger than 40" on a diagonal.

The Cover and Sump combination are rated at the following Maximum Allowable Flow Rates 2" Side Port Floor-Mounted 116 GPM 2" Bottom Port Floor-Mounted 123 GPM 2" Side Port Wall-Mounted 66 GPM 2" Bottom Port Wall-Mounted 59 GPM 1 1/2" Side Port Floor-Mounted 107 GPM 1 1/2" Side Port Wall-Mounted 72 GPM 1 1/2" Bottom Port Floor-Mounted 122 GPM 1 1/2" Bottom Port Wall-Mounted 64 GPM